

PAT Testing Log



26 May 2025
3 pages

www.primetimeaudio.co.uk 07736 415309

Item:	Serial Number	Class	Fuse	Visual Inspection	Earth Continuity/ RPE (Ohms)	Insulation Resistance/ RISO (Megaohms)	Leakage Current/ ILEAK (mA)	Polarity	Functional Check	Pass/Fail	Tester	Date	Retest
Mixing Desks:													
Yamaha DM7	EGEH01212	I	N/A	OK	0.05	>20	0.37	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Yamaha DM7C	EGEM01068	I	N/A	OK	0.06	>20	0.37	N/A	OK	Pass	J Bird	26-May-25	26-May-26
QSC Touchmix	LKE0G2366	I	N/A	OK	0.09	>20	0.59	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Allen&Heath ZED10FX	Z10FFX 467676	I	N/A	OK	0.07	>20	0.47	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Amplifiers:													
QSC PL380 I	021250600	I	OK	OK	0.09	>20	0.66	N/A	OK	Pass	J Bird	26-May-25	26-May-26
QSC PL380 II	120850285	I	OK	OK	0.07	>20	0.63	N/A	OK	Pass	J Bird	26-May-25	26-May-26
QSC PLD 4.5 I	VGE0C0183	I	OK	OK	0.05	>20	0.63	N/A	OK	Pass	J Bird	26-May-25	26-May-26
QSC PLD 4.5 II	VGE0C0164	I	OK	OK	0.06	>20	0.63	N/A	OK	Pass	J Bird	26-May-25	26-May-26
QSC PLD 4.3	011452408	I	OK	OK	0.06	>20	0.66	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Powersoft		I	OK	OK	0.05	>20	0.71	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Rack Units:													
Yamaha Tio1608-D2	BEDY01045	I	N/A	OK	0.07	>20	0.49	N/A	OK	Pass	J Bird	26-May-25	26-May-26
XTA 444		I	OK	OK	0.12	>20	0.54	N/A	OK	Pass	J Bird	26-May-25	26-May-26
APC SC450 UPS		I	N/A	OK	0.05	N/A	N/A	N/A	OK	Pass	J Bird	26-May-25	26-May-26
FisherAmps ALC161	ALC161-11632-2014	I	N/A	OK	0.08	>20	0.05	N/A	OK	Pass	J Bird	26-May-25	26-May-26
RF VENUE	L6803036TIAD4-110	I	N/A	OK	0.06	>20	0.17	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Shure UA844 I	N/A	I	N/A	OK	0.17	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Shure UA844 II	N/A	I	N/A	OK	0.21	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Powered Speakers:													
JBL VRX 932LAP I	PO839-22826	I	N/A	OK	0.12	>20	0.75	N/A	OK	Pass	J Bird	26-May-25	26-May-26
JBL VRX 932LAP II	PO839-22832	I	N/A	OK	0.09	>20	0.51	N/A	OK	Pass	J Bird	26-May-25	26-May-26
YAMAHA DXR I	BEVO01026	I	N/A	OK	0.06	>20	0.51	N/A	OK	Pass	J Bird	26-May-25	26-May-26
YAMAHA DXR II	EEVM01123	I	N/A	OK	0.09	>20	0.39	N/A	OK	Pass	J Bird	26-May-25	26-May-26
YAMAHA DXR III	BEUZ201012	I	N/A	OK	0.07	>20	0.49	N/A	OK	Pass	J Bird	26-May-25	26-May-26
YAMAHA DXR IV	BEUZ01010	I	N/A	OK	0.13	>20	0.49	N/A	OK	Pass	J Bird	26-May-25	26-May-26
TURBOSOUND TXP I	03650012	I	N/A	OK	0.07	>20	0.75	N/A	OK	Pass	J Bird	26-May-25	26-May-26
TURBOSOUND TXP II	N/A	I	N/A	OK	0.06	>20	0.53	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Flightcased Power:													
QSC PL380 1	N/A	N/A	OK	OK	0.08	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
QSC PL380 2	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
PLD Trailing socket	N/A	N/A	N/A	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
PLD IEC I	N/A	N/A	OK	OK	0.08	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
PLD IEC II	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
PLD IEC III	N/A	N/A	OK	OK	0.04	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
UPS Trailing Socket	N/A	N/A	N/A	OK	0.13	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
UPS IEC	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
Shure UA844 PSU	N/A	II	N/A	OK	N/A	>20	0.15	Good	OK	Pass	J Bird	26-May-25	26-May-26
ShureUA844 IEC	N/A	N/A	N/A	OK	0.07	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
FisherAmps IEC	N/A	N/A	N/A	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26

QLXD II trailing socket	N/A	N/A	N/A	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
Trailing Sockets:													
13A-13A 01	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-13A 02	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-13A 03	N/A	N/A	OK	OK	0.11	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-13A 04	N/A	N/A	OK	OK	0.11	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-13A 05	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC Cables:													
IEC 01	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 02	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 03	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 04	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 05	N/A	N/A	OK	OK	0.07	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 06	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 07	N/A	N/A	OK	OK	0.04	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 08	N/A	N/A	OK	OK	0.04	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 09	N/A	N/A	OK	OK	0.07	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 10	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 11	N/A	N/A	OK	OK	0.04	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 12	N/A	N/A	OK	OK	0.02	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 13	N/A	N/A	OK	OK	0.02	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 14	N/A	N/A	OK	OK	0.02	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 15	N/A	N/A	OK	OK	0.01	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 16	N/A	N/A	OK	OK	0.09	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
IEC 17	N/A	N/A	OK	OK	0.07	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
Ceeform:													
13A-16A 01	N/A	N/A	OK	OK	0.09	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-16A 02	N/A	N/A	OK	OK	0.15	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-16A 03	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-16A 04	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-16A 05	N/A	N/A	OK	OK	0.08	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-16A 06	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-16A 07	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 01	N/A	N/A	OK	OK	0.07	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 02	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 03	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 04	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 05	N/A	N/A	OK	OK	0.08	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 06	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 07	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 08	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 09	N/A	N/A	OK	OK	0.05	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 10	N/A	N/A	OK	OK	0.03	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 11	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-13A 12	N/A	N/A	OK	OK	0.04	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 01	N/A	N/A	OK	OK	0.08	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 02	N/A	N/A	OK	OK	0.12	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 03	N/A	N/A	OK	OK	0.09	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 04	N/A	N/A	OK	OK	0.08	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 05	N/A	N/A	OK	OK	0.09	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 06	N/A	N/A	OK	OK	0.07	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 07	N/A	N/A	OK	OK	0.08	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 08	N/A	N/A	OK	OK	0.15	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 09	N/A	N/A	OK	OK	0.13	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 10	N/A	N/A	OK	OK	0.09	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26

16A-16A 11	N/A	N/A	OK	OK	0.14	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 12	N/A	N/A	OK	OK	0.12	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
16A-16A 13	N/A	N/A	OK	OK	0.13	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
Powercon													
13A-Powercon 1	N/A	N/A	OK	OK	0.09	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-Powercon 2	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-Powercon 3	N/A	N/A	OK	OK	0.08	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
13A-Powercon 4	N/A	N/A	OK	OK	0.06	>20	N/A	Good	OK	Pass	J Bird	26-May-25	26-May-26
PSUs:													
Macbook PSU	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
HP Pavilion	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
HP Spectre	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
DMX controller PSU	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
tp-link PSU	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
IEM 01	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
IEM 02	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
IEM 03	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
IEM 04	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
IEM 05	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
IEM 06	N/A	II	OK	OK	N/A	>20	0.10	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Lighting:													
XBRICK 1	N/A	I	OK	OK	0.07	>20	0.53	N/A	OK	Pass	J Bird	26-May-25	26-May-26
XBRICK 2	N/A	I	OK	OK	0.09	>20	0.51	N/A	OK	Pass	J Bird	26-May-25	26-May-26
XBRICK 3	N/A	I	OK	OK	0.08	>20	0.54	N/A	OK	Pass	J Bird	26-May-25	26-May-26
XBRICK 4	N/A	I	OK	OK	0.13	>20	0.53	N/A	OK	Pass	J Bird	26-May-25	26-May-26
Pearl Piver PR150 I	400229 001100 4080074	N/A	OK	OK	0.15	>20	0.52	Good	OK	Pass	J Bird	26-May-25	26-May-26
Pearl Piver PR150 II	400131 001000 4070067	N/A	OK	OK	0.09	>20	0.37	Good	OK	Pass	J Bird	26-May-25	26-May-26
Pearl Piver PR150 III	400131 001000 4070043	N/A	OK	OK	0.06	>20	0.51	Good	OK	Pass	J Bird	26-May-25	26-May-26
Pearl Piver PR150 IV	400131 001000 4070117	N/A	OK	OK	0.08	>20	0.36	Good	OK	Pass	J Bird	26-May-25	26-May-26
HZ-200 haze machine	(21)74606XGB00148	N/A	OK	OK	0.06	>20	0.10	Good	OK	Pass	J Bird	26-May-25	26-May-26
Laserworld EL-300	81811182	N/A	OK	OK	0.06	>20	0.10	Good	OK	Pass	J Bird	26-May-25	26-May-26